

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Application of:)
YASUFUMI ASAOK) : Examiner: B. Healy
Application No.: 10/552,578) : Group Art Unit: 2883
Filed: July 30, 2004) : Confirmation No.: 2530
For: DISPLAY APPARATUS) : April 14, 2009
U.S. Patent No. 7,423,711 B2) :
Issued: September 9, 2008) :

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

**REQUEST FOR
CERTIFICATE OF CORRECTION
UNDER RULE 323**

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of mistakes which are not the fault of the Patent and Trademark Office. A Certificate of Correction form is attached.

The statutory fee of \$100.00 is being paid electronically. Any additional fee required by this paper may be charged to Deposit Account No. 06-1205.

Patentee's undersigned attorney may be reached in our Washington, D.C. office by telephone at (202) 530-1010. All correspondence should continue to be directed to our below-listed address.

Respectfully submitted,

/Scott D. Malpede/

Scott D. Malpede
Attorney for Patentee
Registration No. 32,533

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
Facsimile: (212) 218-2200

SDMvnm

FCHS_WS 2718668v1

Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 7,423,711 B2

DATED : September 9, 2008

INVENTOR(S) : YASUFUMI ASAO

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 2:

Line 30, "shinning" should read --shining--.

Line 35, "shinning" should read --shining--.

Line 40, "shinning" should read --shining--.

COLUMN 4:

Line 29, "to a" should read --to as--.

COLUMN 6:

Line 57, "type" should read --types--.

COLUMN 8:

Line 14, "crystal device" should read --crystal--.

Line 50, "state" should read --state that--.

COLUMN 9:

Line 43, "state" should read --state that--.

COLUMN 10:

Line 44, "state" should read --state that--.

COLUMN 11:

Line 3, "type" should read --types--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 7,423,711 B2

No. of add'l. copies
@ 30¢ per page



Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 7,423,711 B2

DATED : September 9, 2008

INVENTOR(S) : YASUFUMI ASAO

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 12:

Line 43, "state" should read --state that--.

COLUMN 13:

Line 36, "state" should read --state that--.

COLUMN 14:

Line 30, "state" should read --state that--.

COLUMN 16:

Line 35, "may" should read --may be--.

Line 41, "them" should read --than--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 7,423,711 B2

No. of add'l. copies
@ 30¢ per page

